

# **VOLUMETRIC INSTRUMENTS AND ACCESSORIES**











### **Clamps**

made of zinc die cast, without bosshead, with round jaws Handle (hollow) approx. 150 x 12 mm, total length 240 mm

**40865010** Opening up to approx. 12 - 25 mm **40865040** Opening up to approx. 20 - 40 mm

#### **Clamps**

made of zinc die cast, without bosshead, with round jaws Handle (hollow) approx.  $150 \times 12 \text{ mm}$  Ø, total length 260 mm

**40866010** Opening up to approx. 38 - 60 mm

## Rings without bosshead

made of malleable iron

Handle (hollow) approx. 180 x 12 mm  $\emptyset$ 

	Inside Ø	Outside Ø
40868007	approx. 50 mm	approx. 70 mm
40868010	approx. 80 mm	approx. 100 mm
40868013	approx. 110 mm	approx. 130 mm

#### Rings with bosshead

made of malleable iron, for rods up to 16 mm Ø

	Inside Ø	Outside Ø
40869007	approx. 50 mm	approx. 70 mm
40869010	approx. 80 mm	approx. 100 mm
40869013	approx. 110 mm	approx. 130 mm

### **Burette clamps for one burette**

made of zinc die cast, with bosshead Opening up to approx. 20 mm

**40870010** for rods up to 13 mm Ø

# **Burette clamps for two burettes**

made of zinc die cast, with bosshead Opening up to approx. 20 mm

**40871010** for rods up to 13 mm Ø